

Complete Mould Eradication & Prevention System



MOULD REMOVAL IN 3 EASY STEPS



1. SPRAY

Spray MCS1 Mould Clear solution onto the affected surface from a distance of **3 – 5cms**.

Treat visible mould plus **1 meter** beyond.

Repeat the treatment on badly affected areas after **10 – 15 minutes**.



2. WIPE

Rub the surface using the sponge provided. Allow approximately 30 minutes for the product to work, then rinse with warm soapy water. Repeat treatment if necessary.



3. PAINT ADDITIVE

Add 100ml of MCS 3 Paint Additive to 5L of water based paint (emulsion, vinyl, silk or matt) or add 50ml MCS3 Paint Additive to 5 L of solvent based paint (primer, undercoat or gloss). Blend the paint Additive until fully dispersed, for at least 1 minute. Apply the paint in accordance with the manufacturer's instructions.